

CASE STUDY

VEHICLE: HOLDEN ASTRA



ACCIDENTAL PHOTOS – FRONT & REAR



POST REPAIRED PHOTOS-FRONT & REAR

Summary

This is a classic case where the Insurance group is the insurer, assessor, and the repairer of this vehicle. This vehicle was repaired by the insurer against all odds, putting profit over safety. The concerned client contacted IVIC for a Free Post Repair Inspection. IVIC's inspection report conducted on the vehicle and found that it is ticking all boxes but, for all the wrong reasons. There were **61 defects** detected in the report and mostly structural. This vehicle will not sustain another crash and will crumble, putting every occupant of the vehicle at risk possible death.

IVIC has successfully removed one more unsafe vehicle off the road.

Do not become a statistic, Contact IVIC today for a Free vehicle Inspection on 1300 00 IVIC (4842)